

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO : 6,939,178 *B2*

DATED : September 6, 2005

INVENTOR(S) : Robert Raymond Arcykiewicz et al.

It is certified that an error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

*X/O*  
*NOTE*  
*NOTE*  
On the face of the patent, under "(56) References Cited, column 2, correct the name of the inventor of U.S. Patent No. 6,328,321 to --Ording et al.--; same line, change the U.S. Cl. from "280/86.754" to --239/585.1; 239/590.3--.

*36*  
Col. 1, line *36*, change "problem" to --problems--;

*53*  
line *47*, change "add" to --and--.

Col. 2, line 23, change "a identification" to --an identification--.

Col. 5, lines 19 and 21, change "male pins" to --male plugs--;

line 30, change "as" best shown" to --as best shown--.

Col. 6, claim 1, line 39, after "assembly" insert a semi-colon --;--.

Col. 8, claim 10, line 5, after "assembly" insert a semi-colon --;--.

*A*  
*C*  
*A*  
*C*  
*I*  
*A*  
*I*

MAILING ADDRESS OF SENDER:

PATENT NO. 6,939,178

No. of add'l copies @ \$.30 per page

BLANK ROME LLP  
600 NEW HAMPSHIRE AVENUE, N.W.  
WASHINGTON, DC 20037  
TEL (202) 944-3000  
FAX (202) 572-8398

⇒ \_\_\_\_\_

FEB 14 2006



UNITED STATES PATENT AND TRADEMARK OFFICE

---

Commissioner for Patents  
United States Patent and Trademark Office  
P.O. Box 1450  
Alexandria, VA 22313-1450  
[www.uspto.gov](http://www.uspto.gov)

Date Mailed : February 17, 2006

Patent No. : 6,939,178 B2  
Inventor : Arcykiewicz, Robert R.  
Patent Issued : September 6, 2005  
Title : FUEL INJECTOR CONNECTOR  
Docket No. : 111418-00410

Re: Request for Certificate of Correction

Consideration has been given your request for the issuance of a certificate of correction for the above-identified patent under the provisions of Rule 1.322.

Inspection of the file of the application for the patent reveals that the cover sheet, field (56) is/are printed in accordance with the record in the Patent and Trademark Office, as passed to issue by the examiner. The inventor of Pat. No. 6,328,321 is in fact named Nolan. There being no fault on the part of the Patent and Trademark Office, it has no authority to issue a certificate of correction under the provision of 1.322.

A certificate of correction will be issued to correct the error(s) noted in your request.

Future correspondence concerning this matter should be filed and directed to Decisions & Certificates of Correction Branch.

Commissioner of Patents  
P.O. Box 1450  
Alexandria, VA 22313-1450  
Attn: Certificates of Correction Branch

David Irvine  
Cecilia Newman, Supervisor  
Decisions & Certificates of Correction Branch  
703/308-9590 or 703/305-4362 (Fax 703/273-9927)

Charles R. Wolfe, Jr.  
Blank Rome LLP  
Watergate, 600 New Hampshire Ave. N.W.  
Washington, DC 20037  
CBN/ di